

The cold  
frosty  
morning  
revealed  
lines of the  
timber  
joists in the  
ceiling  
plasterwork



# East Church – Moving to new heights

23 January 2009



A close look at the church roof reveals the cause of some of the problems. Gutters and valleys are filled with debris, preventing them from draining properly, so that rainwater runs down the walls adding to the dampness in the church.

The moss and stonecrop clumps look beautiful but add to the build up in the gutters as they slide off the roof. Regular maintenance is the simplest solution.

The lichens however are pure asset!



# Looking after the Kirkyard

## Join Us!



*Come and join us at the church at 13.30 on Monday 2 March 2009* when Archaeology Scotland's 'Adopt a Monument' Officer Helen Bradley will be coming up to Cromarty to help us to set up a graveyard recording scheme and describe how volunteers can draw up a conservation plan for the grounds.

If you're interested either turn up on the day - or ideally get in touch with either Caroline or David so that they can make sure there are enough cakes for afternoon tea!

*You can get in touch with them by phoning 01381 600243 or email [info@eastchurchcromarty.co.uk](mailto:info@eastchurchcromarty.co.uk)*

